

APPLICATION AND REFERRAL TO THE US COMMISSION OF FINE ARTS FOR OLD GEORGETOWN REVIEW

OG		
НРА		

The Old Georgetown Act of 1950 requires the District of Columbia to refer construction plans to the US Commission of Fine Arts (CFA) for review before a building permit is issued. Work in Georgetown is also subject to a coordinated historic preservation review under the DC Historic Landmark and Historic District Protection Act of 1978. To initiate these reviews, please submit this form with all required attachments as directed below.

	THIS IS A REQUEST FOR THE FOLLOWING REVIEW BY THE COMMISSION OF FINE ARTS:								
	THIS IS A REQUEST FOR THE FOLLOWING REVIEW BY THE COMMISSION OF FINE ARTS:								
	CONCEPTUAL REVIEW to receive guidance at the early stages of design								
	□ PERMIT REVIEW to receive a recommendation on a building permit application								
1.	OWNER, APPLICANT, AND PROPERTY INFORMATION								
	Property Owner's Name: Live Oak Trust u/a/d 3/25/2010								
	Applicant's Name (if different from owner): Michael Patrick, AIA								
	Project Address: 3238 & 3232 R Street NW, Washington, DC 20007								
	Square: 1280 Lot: 1015								
	To find your square and lot, see www.propertyquest.dc.gov								
	□ I am currently the owner of the property								
	□ I am a homeowner currently receiving the DC homestead deduction for this property								
	I am an authorized representative of the property owner								
	☐ I am or represent a potential purchaser of the property								
2.	SUBMISSION MATERIALS FOR THE COMMISSION OF FINE ARTS AND HISTORIC PRESERVATION REVIEW								
	The following materials are included with this application:								
	Two (2) sets of comprehensive exterior photographs of the building, structure, or site and its context (showing adjacent buildings, immediate surroundings, and the areas of proposed work)								
	For each of the following, two (2) copies for a concept application or five (5) copies for a permit application:								
	☐ Site plan showing the existing footprint of the property and adjacent buildings								
	Building plans, elevations, and site plan sufficient to illustrate the footprint, height, massing, design, and materials of the proposed work and its surrounding context								
	For more information on submission requirements, see www.cfa.gov or contact the CFA staff at 202-504-2200								
3.	PROJECT DESCRIPTION (CHECK ALL THAT APPLY)								
	\square Addition \boxtimes Exterior Alteration \square New Construction \square Subdivision \square Other								
	Briefly describe the nature of the project: Renovations to five (5) strutures on the historic "Scott-Grant House"								
	property, for maintenance and protection of historic fabric, restoration of certain elements changed over time,								
	and upgrading of modern structures to a more compatible condition.								
	Yes No Unsure								
	Is the proposed work visible from a public street or alley? $\ \ \ \ \ \ \ \ \ \ \ \ \ $								
	Will there be work on the front of the building or in the front yard? $X \square \square$								
	Does the project include work in public space?								
	Does the project include removal of roof or floor framing or bearing walls? historic								
	Is this a Fair Housing Act request for "reasonable accommodation"?								
	(over)								

4. ADDITIONAL INFORMATION FOR LARGER PROJECTS

For renovation or new construction projects exceeding 20,000 square feet, attach a full narrative description indicating the general nature of the project, program of uses, estimated gross floor area by use, number of residential units, scope of preservation work, and any other pertinent features or benefits, including aspects of sustainability. Homeowners proposing work on their own house do not need to provide this information.

YES	⊠ □ No	□ □ Unsure			
YES					
	No	Unsure			
□ C at 202 -33	□ 88-7427				
YES	No	Unsure			
	X				
	X				
8. CONTACT INFORMATION Owner Address (if different from project address):201 Main Street Suite 3100, Fort Worth, TX 76102 Owner Phone:650-581-8706 / 650-799-3449 Owner Email:mf@keystoneco.com Agent's Capacity: Tenant Architect Contractor Contract Purchaser Expediter Other Agent Address (if different from owner):BarnesVanze Architects, 1000 Potomac St NW, STE L2, Washington DC 20007 Agent Phone:202-337-7255 / 202-494-6639					
	YES	TX 76102 C at 202-338-7427 YES NO			

When completed, submit this form with all plans, photographs, and other attachments to the Historic Preservation Office (HPO) desk at the DC Permit Center, Department of Consumer and Regulatory Affairs, 1100 4th Street SW, 2nd floor. Upon review of this submission, CFA or HPO staff may contact the owner or agent for consultation, and may request additional information if determined necessary to review the project.

Referral to CFA or the Historic Preservation Review Board, if required, may be deferred if information is not received within sufficient time to allow staff evaluation and preparation for review. All application materials are part of the public record and are made available to the public for inspection. For more information, see www.cfa.gov or www.preservation.dc.gov.



Historic Preservation Office DC Office of Planning (202) 442-8800 historic.preservation@dc.gov



FULL DRAWING INDEX:

A3.5

A3.6

THE SCOTT-GRANT HOUSE AND ITS FOUR DEPENDENT STRUCTURES HAVE HELD AN IMPORTANT PLACE IN THE HISTORY OF GEORGETOWN AND THE UNITED STATES. OCCUPIED VARIOUSLY BY PROMINENT PRIVATE HOMEOWNERS, UNITED STATES PRESIDENTS (HOWEVER BRIEFLY), AND INFLUENTIAL PARTY WORKING GROUPS, THE HOUSE ON THE HILL KNOWN AS LEE HILL BEFORE THE CIVIL WAR, THEN AS THE PROPERTY NEXT TO THE RESERVOIR, AND THAT IS NOW ADJACENT TO THE GEORGETOWN PUBLIC LIBRARY, HAS GRACED THE CITY FROM 1857 TO TODAY THROUGH PERIODS OF UPHEAVAL AND PROSPERITY.

THE MAIN HOUSE, AS THE SCOTT-GRANT HOUSE IS REFERRED TO IN THIS SUBMISSION, WAS CONSTRUCTED IN 1857 AS AN ITALIANATE VILLA, WITH A CHARMING COTTAGE OF THE SAME DATE CONSTRUCTED AS A GUEST HOUSE ON THE EDGE OF THE HILL TOWARD THE REAR. THE MAIN HOUSE WAS RENOVATED IN 1901, CREATING A GEORGIAN / FEDERAL DECORATIVE THEME OVER THE PREVIOUS ITALIANATE DESIGN, FOLLOWED CLOSELY IN 1910 BY THE CONSTRUCTION OF A NEW GARAGE AND ATTACHED LAUNDRY AND WORKSHOP BUILDING AROUND A COBBLESTONE SERVICE AND DRIVE COURT. IN 1975, A 70'S-STYLE 3-BEDROOM RESIDENCE, NOW CALLED THE GUARD HOUSE, WAS CREATED ACROSS THE DRIVE AND SLIGHTLY DOWN THE HILL ON A SEPARATE LOT, BUT NEXT TO THE MAIN HOUSE. ALTHOUGH NOT VISUALLY CONSISTENT WITH THE CHARACTER OF THE OTHER STRUCTURES, THIS PROVIDES EVEN TODAY A USEFUL AMENITY FOR THE PROPERTY AND THE STREET.

IN THE 1990'S, RENOVATIONS WERE CARRIED OUT ON THE MAIN HOUSE AND COTTAGE FOR THE PURPOSE OF MAINTENANCE AND REPAIR. THE INTERIOR OF THE MAIN HOUSE WAS LARGELY GUTTED AND REPLACED WITH MODERN MATERIALS AND MECHANICAL SYSTEMS. SINCE THAT TIME, DETERIORATION HAS CONTINUED ON THE OTHER STRUCTURES, AND IN SOME CASES THREATENS THE BUILDINGS IF UPDATES AND RENOVATIONS ARE NOT CARRIED OUT IN THE NEAR FUTURE. RECENT RUPTURED PIPING IN THE MAIN HOUSE ALSO CAUSED DAMAGE THROUGHOUT TO THE MODERN INTERIOR, WHICH WILL BE ADDRESSED IN THE PROJECT.


THE OWNERS OF THE PROPERTY HAVE ASKED BYA / BARNESYANZE ARCHITECTS TO ORGANIZE THIS RENOVATION EFFORT. THE INTENT ON THE WHOLE IS TO STABILIZE THE FIVE STRUCTURES WHERE NEEDED AND PRESERVE THE HISTORIC FABRIC FOR THE NEXT GENERATIONS, WHILE MAKING SMALL CORRECTIONS TO WHAT APPEAR TO BE UNFORTUNATE CHANGES THAT HAVE BEEN MADE OVER TIME. IN THE CASE OF THE GUARD HOUSE, DETERIORATION IS ADVANCED, THE ROOF, WINDOWS AND DOORS WILL NEED TO BE REPLACED, AND WE ARE PROPOSING THAT THE EXTERIOR DESIGN BE HARMONIZED IN THE PROCESS WITH THE OLDER STRUCTURES ON THE SITE.

EACH BUILDING IS TREATED IN THIS SUBMISSION IN TURN, IN THE ORDER OF ITS CONSTRUCTION.

NO DESIGN CHANGES ARE PROPOSED TO THE SITE, OTHER THAN TO ADD A NEW TREE IN THE BACK YARD, HOWEVER, BEHIND THE GARAGE AND BETWEEN THE GARAGE AND LAUNDRY AND WORKSHOP BUILDING, THERE IS SIGNIFICANT HEAVING IN THE PAVING AND LANDSCAPE THAT WILL BE REPAIRED.

> GENERAL DATA SHEET FLOOR PLANS EXTERIOR ELEVATIONS

SITE LOCATION ENLARGED AREA MAP:



DETAILED VICINITY MAP:

SHEET #	DRAWING NAME	SHEET # (CONT.)	DRAWING NAME (CONTINUED)
AO.1	OVERALL PROJECT - GENERAL DATA SHEET	A4.1	WORKSHOP AND LAUNDRY - GENERAL DA
AO.2	OVERALL PROJECT - SITE PLAN	A4.2	WORKSHOP AND LAUNDRY - FLOOR PLAN
		A4.3	WORKSHOP AND LAUNDRY - EXTERIOR EL
A1.1	MAIN HOUSE - GENERAL DATA SHEET		
A1.2	MAIN HOUSE - FLOOR PLANS	A5.1	GUARD HOUSE - GENERAL DATA SHEET
A1.3	MAIN HOUSE - FLOOR PLANS	A5.2	GUARD HOUSE - FLOOR PLANS
A1.4	MAIN HOUSE - FLOOR PLANS	A5.3	GUARD HOUSE - FLOOR PLANS
A1.5	MAIN HOUSE - FLOOR PLANS	A5.4	GUARD HOUSE - FLOOR PLANS
A1.6	MAIN HOUSE - FLOOR PLANS	A5.5	GUARD HOUSE - FLOOR PLANS
A1.7	MAIN HOUSE - EXTERIOR ELEVATIONS	A5.6	GUARD HOUSE - EXTERIOR ELEVATIONS
Al&	MAIN HOUSE - EXTERIOR ELEVATIONS	A5.7	GUARD HOUSE - EXTERIOR ELEVATIONS
A1.9	MAIN HOUSE - EXTERIOR ELEVATIONS		
A1.10	MAIN HOUSE - EXTERIOR ELEVATIONS		
A1.11	MAIN HOUSE - EXTERIOR ELEVATIONS		
A2.1	COTTAGE - GENERAL DATA SHEET		
A2.2	COTTAGE - FLOOR PLANS		
A2.3	COTTAGE - EXTERIOR ELEVATIONS		
40.			
A3.1	GARAGE - GENERAL DATA SHEET		
A32	GARAGE - FLOOR PLANS		
A3.3	GARAGE - FLOOR PLANS		
I ∆3.4	GARAGE - FLOOR PLANS		

CONTEXT PHOTO: EXISTING PANORAMA

GARAGE - EXTERIOR ELEVATIONS

GARAGE - EXTERIOR ELEVATIONS



EXISTING 3200 BLOCK OF R STREET NW (SOUTH SIDE)

BUILDING LOCATION KEY:

DCRA STAMP:

(NTS)

GRAPHIC SCALE:


R STREET N

2156

Trust

drawing: GENERAL DATA SHEET Oak Live

BUILDING#:



BUILDING SCOPE:


THE MAIN HOUSE, ALSO KNOWN AS THE SCOTT-GRANT HOUSE AND REFERRED TO AS BUILDING I IN THIS SUBMISSION. 15 AN EXISTING 3 STORY BRICK STRUCTURE BUILT IN 1857. HISTORIC PHOTOS SHOW THAT ORIGINALLY A GRAND EXTERIOR STAIRCASE ROSE FROM THE R STREET SIDE (THEN CALLED ROAD STREET) TO A DOUBLE DOOR FRONT ENTRANCE WITH TRANSOM IN ITALIANATE STYLE, ON THE PIANO NOBILE LEVEL. THE BYA TEAM HAS SURMISED THAT THE INTERIOR MAIN HALL ON THIS LEVEL ORIGINALLY CONNECTED DIRECTLY TO THE GRACIOUS COVERED PORCH ON THE BACK OF THE HOUSE, BUT NO EVIDENCE HAS BEEN RECOVERED TO SUPPORT THIS, OTHER THAN THE PRESENCE OF FEDERAL STYLE DETAILING ON WHAT MAY HAVE BEEN A REPLACEMENT OF AN ORIGINAL DOOR AT THIS CONNECTION POINT ON THE BACK PORCH.

BY 1907, THAT EXTERIOR STAIR HAD BEEN REMOVED, AND THE MAIN ENTRANCE TO THE HOUSE REESTABLISHED ON THE GROUND FLOOR, WITH A FEDERAL STYLE WINDOW OCCUPYING WHAT HAD BEEN THE FRONT DOOR ABOVE. GIVEN THE LACK OF CERTAIN EVIDENCE OF AN OLDER INTERIOR CONFIGURATION, BYA PROPOSES TO MAINTAIN THIS CURRENT CONDITION, WHICH ON THE EXTERIOR AT LEAST, NOW HAS A 100+ YEAR HISTORY.

THE TEAM HAS EXPLORED OTHER CONNECTIONS FROM THE HOUSE INTERIOR TO THE BACK PORCH AND DETERMINED THAT THE TALL SIX-OVER-NINE SASH WINDOWS ALONG THE BACK, AND FRONT, OF THE MAIN LEVEL POCKET UP INTO THE WALL, ALLOWING DIRECT ACCESS FROM THE LIVING ROOM TO THE PORCH. THIS APPEARS TO BE AN EXISTING CONDITION THAT HAPPILY IS IN WORKING ORDER TODAY. THIS ALLOWS PASSAGE FROM THE MAIN LIVING AREAS ON THE MAIN FLOOR TO THE BACK PORCH. THE ONLY EXTERIOR CHANGE PROPOSED IN THIS SUBMISSION IS TO RESTORE THE SINGLE OPENING FROM THE DINING ROOM ON THE OTHER SIDE OF THE HOUSE BACK TO THIS SAME WINDOW. IT IS CURRENTLY A DOOR AND TRANSOM OF MORE RECENT ORIGIN.

OTHERWISE, THE MAIN HOUSE WILL RECEIVE ONLY MASONRY REPOINTING, AND ROOF AND OTHER REPAIRS, AS NEEDED. THE INTERIOR WILL RECEIVE A GENERAL REFRESH TO ALL NON-ORIGINAL FINISHES, AND REPAIRS TO THE HVAC SYSTEM AND OTHER SYSTEMS WHICH HAVE FAILED OR NEED TO BE UPDATED.

REFERENCE PHOTOS KEY:




REFERENCE PHOTOS: EXISTING EXTERIOR ELEVATIONS TO REMAIN



ELEVATION DETAIL - EXISTING ITALIANATE HOOD



ELEVATION DETAIL - EXISTING GEORGIAN WINDOW



NORTH ELEVATION - STREET VIEW



NORTH ELEVATION



WEST ELEVATION



SOUTH ELEVATION



EAST ELEVATION

BUILDING LOCATION KEY: (NTS)

DCRA STAMP:

GRAPHIC SCALE:

drawing: GENERAL DATA SHEET

MAIN HOUSE

BUILDING#:


R STREET NW


2156

Trust


Oak

3238 R Street NW Washington, DC 20 Live





BUILDING#:
BUILDING 1



BUILDING LOCATION KEY: (NTS) R STREET NW

DCRA STAMP:

GRAPHIC SCALE:

0 5

2156


Live Oak Trust
3238 R Street NW
Washington, DC 20007

DRAWING: SECOND FLOOR EXISTING PLAN

SHEET #:

BUILDING#:
BUILDING 1

BUILDING NAME: MAIN HOUSE



BUILDING LOCATION KEY: (NTS) R STREET NW

DCRA STAMP:


GRAPHIC SCALE:

2156

Live Oak Trust
3238 R Street NW
Washington, DC 20007

DRAWING: ATTIC EXISTING PLAN OGB CONCEPT REVIEW OGB CONCEPT REVIEW R

BUILDING NAME: MAIN HOUSE



DCRA STAMP:

2156


Live Oak Trust
3238 R Street NW
Washington, DC 20007

DRAWING: ROOF EXISTING PLAN

OGB CONCEPT REVIEW OGB CONCEPT REVIEW R

#: HSSUED: BUILDING#:

BUILDING NAME: MAIN HOUSE



BUILDING LOCATION KEY: (NTS)

DCRA STAMP:

GRAPHIC SCALE:

R STREET NW


2156

DRAWING:
NORTH EXTERIOR
EXISTING ELEVATION

Live Oak Trust
3238 R Street NW
Washington, DC 20007

BUILDING NAME: MAIN HOUSE

BUILDING#:
BUILDING 1



DCRA STAMP: NO PROPOSED CHANGES BUILDING LOCATION KEY: (NTS) R STREET NW GRAPHIC SCALE: 2156 Live Oak Trust
3238 R Street NW
Washington, DC 20007 DRAWING: EAST EXTERIOR EXISTING ELEVATION FIRST FLOOR BUILDING NAME: MAIN HOUSE GROUND FLOOR

BUILDING#:
BUILDING 1

(C2) MAIN HOUSE - EXISTING PARTIALLY BELOW GRADE EAST ELEVATION

1/8" : 1'-0" WHEN PRINTED AT 22"/36"
1/8" : 1'-0" WHEN PRINTED AT 11"XIT"

SHEET #:

CI MAIN HOUSE - EXISTING EAST ELEVATION

A1.8 1/4" : 1'-0" WHEN PRINTED AT 22"x36"

1/8" : 1'-0" WHEN PRINTED AT 11"x17"

SECOND FLOOR


FIRST FLOOR

GROUND FLOOR

LOWER LEVEL

EXCEPT AT DOOR FROM DINING


ROOM TO BACK PORCH AS NOTED



BUILDING LOCATION KEY: (NTS) R STREET NW

DCRA STAMP:

GRAPHIC SCALE:



2156

Live Oak Trust
3238 R Street NW
Washington, DC 20007

DRAWING: SOUTH EXTERIOR PROPOSED ELEVATION

BUILDING NAME: MAIN HOUSE

BUILDING#:
BUILDING 1

DCRA STAMP: NO PROPOSED CHANGES BUILDING LOCATION KEY: (NTS) R STREET NW GRAPHIC SCALE: SECOND FLOOR 2156 Live Oak Trust
3238 R Street NW
Washington, DC 20007 DRAWING: WEST EXTERIOR EXISTING ELEVATION FIRST FLOOR GROUND FLOOR BUILDING NAME: MAIN HOUSE GROUND FLOOR BUILDING#:
BUILDING 1 SHEET #: CI MAIN HOUSE - EXISTING WEST ELEVATION


| 1/4" : 1'-0" WHEN PRINTED AT 22"/36" |
| 1/6" : 1'-0" WHEN PRINTED AT 11"XIT" | MAIN HOUSE - EXISTING PARTIALLY BELOW GRADE WEST ELEVATION

1/4" = 1'-0" WHEN PRINTED AT 22"+32"

1/8" = 1'-0" WHEN PRINTED AT 11"*XIT"

THE COTTAGE, REFERRED TO AS BUILDING 2 IN THIS SUBMISSION, IS AN EXISTING I STORY BRICK STRUCTURE WITH LOFT BUILT CIRCA 1857, AT THE SAME TIME AS THE MAIN HOUSE.

THE STRUCTURE IS LOCATED BEHIND THE MAIN HOUSE ON THE BROW OF THE HILL WHERE IT BEGINS TO SLOPE DOWN FROM THE RELATIVELY FLAT REAR LAWN. IT IS IN RELATIVELY GOOD CONDITION, AND WE ARE NOT PROPOSING ANY CHANGES TO THE EXTERIOR. THERE ARE A FEW PLACES THAT MAY REQUIRE MASONRY REPAIR, AND THE BACK PORCH MAY NEED SOME STRUCTURAL STABILIZATION, AS THERE IS SOME MOVEMENT IN THE PATIO FLOOR AND ONE CORNER OF THE PORCH. MINOR ROOF REPAIRS MAY BE NEEDED. THIS SUBMISSION DOES NOT PROPOSE CHANGES TO THIS BUILDING.



REFERENCE PHOTOS KEY:

(6)

REFERENCE PHOTOS: EXISTING EXTERIOR ELEVATIONS TO REMAIN







NORTH ELEVATION

PARTIAL WEST ELEVATION

SOUTH WEST ELEVATION ໌ 3 ີ







SOUTH ELEVATION

EAST ELEVATION

NORTH EAST ELEVATION

DCRA STAMP:

BUILDING LOCATION KEY: (NTS) R STREET NW

GRAPHIC SCALE:


DRAWING: GENERAL DATA SHEET

BUILDING#:

2156

Trust

Live Oak 7 3238 R Street NW Washington, DC 20007



SECOND FLOOR

FIRST FLOOR





C2 COTTAGE - EXISTING WEST ELEVATION

1/4" = 1'-0" WHEN PRINTED AT 12" 126"
1/8" = 1'-0" WHEN PRINTED AT 11" INT"

SECOND FLOOR

R STREET NW GRAPHIC SCALE: 2156 DRAWING: EXISTING ELEVATIONS BUILDING NAME: COTTAGE

BUILDING#:

SHEET #:

CI COTTAGE - EXISTING SOUTH ELEVATION

1/4" : 1'-0" WHEN PRINTED AT 12"x36"

1/6" : 1'-0" WHEN PRINTED AT 11"x17"

A1 COTTAGE - EXISTING NORTH ELEVATION

| 1/4" : 1 -0" WHEN PRINTED AT 12" -36" | 1/6" : 1'-0" WHEN PRINTED AT 11" | 1/17" |

DCRA STAMP:

BUILDING LOCATION KEY:

Live Oak Trust
3238 R Street NW
Washington, DC 20007

THE GARAGE, REFERRED TO AS BUILDING 3 IN THIS SUBMISSION, IS AN EXISTING 2 STORY BRICK STRUCTURE BUILT IN 1910.

THE GARAGE INTERIOR IS IN VERY POOR CONDITION, WITH ROOF LEAKS OVER THE YEARS CAUSING ROTTED ROOF BEAM CONDITIONS, AND WIDESPREAD INTERIOR DETERIORATION. INTERIOR RENOVATIONS WILL INCLUDE SOME RECONFIGURATION OF THE INTERIOR SPACE, PRESERVING AND UPGRADING EXISTING BATHROOM AND KITCHEN AMENITIES

THE PROPOSED EXTERIOR WORK INCLUDES RESTORATION OF A MORE ORIGINAL OR COMPATIBLE CONDITION AT THE GARAGE DOOR OPENINGS AND AT THE CENTRAL SECOND STORY WINDOW ABOVE THEM, AND RESTORATION OF THE EXISTING REAR WOODEN EXTERIOR STAIR IN A SIMILAR SPIRIT, AS WELL AS EXTENSIVE REPAIR WORK ON THE ROOF, REPAIR OF HISTORIC WINDOWS, AND REPAIR AND REPOINTING AS NECESSARY OF MASONRY WALLS.

GARAGE DOORS

AT SOME POINT THE GARAGE DOOR OPENINGS WERE FITTED WITH THE CURRENT PEDESTRIAN DOORS AND SIDE LITES, WHICH INCLUDED AN ADDED CONTINUOUS OVERHEAD SUPPORT EXTENDING OUT FROM THE ORIGINAL FACE OF BRICK AND COVERED IN A METAL FLASHING WHICH TODAY HAS AN UNATTRACTIVE APPEARANCE. STONE COBBLEG WERE ADDED AT THE BASE OF THE BRICK PIERS, WHICH WERE PADDED OUT WITH NEW BRICK MASONRY AROUND THE SIDES OF THE NEW DOORS. THE PROPOSED DESIGN REMOVES ALL OF THIS NEWER CONSTRUCTION AND ATTEMPTS TO FIND AND RESTORE THE ORIGINAL BRICK OPENING CONSTRUCTION BEHIND. THERE ARE NO PHOTOGRAPHS SHOWING ORIGINAL DOORS. AN INSPIRATION PHOTOGRAPH WAS SELECTED TO GUIDE THE INTENT OF THE DOOR RESTORATION, WITH CHAMFERED EDGES ON WOOD STILES AND RAILS AND NARROW VERTICAL BOARD PANELS. SIMILAR CHAMFERING WAS FOUND ON THE FEW REMAINING WOODEN STAIR POST PARTS ON THE BACK OF THE BUILDING, WHICH WE BELIEVE TO BE ORIGINAL.

AS THE GARAGE DOOR OPENINGS, AND THE GARAGE DEPTH, ARE TOO SMALL FOR MOST MODERN CARS, THE USE OF THE GROUND FLOOR SPACE HAS BEEN CONCEIVED AS OFFICE SPACE, AND THEREFORE SOME GLASS HAS BEEN INCLUDED IN THE TOP OF EACH OF THE FOUR NARROW DOOR PANELS IN EACH OPENING.

SECOND FLOOR OPENING

BVA HAS STUDIED THE CENTER UPPER WINDOW OPENING, WITH ITS STILL EXTANT WOODEN BEAM FOR HOISTING MATERIALS TO THE SECOND FLOOR SPACE, PARTICULARLY AS IT IS SUBSTANTIALLY WIDER THAN USUAL. NO HISTORIC PHOTOS OF SIMILARLY WIDE WAREHOUSE-TYPE HOIST DOORWAYS COULD BE FOUND. ALL THE EXAMPLES WE COULD FIND DO HAVE A DOUBLE LEAF DOOR BUT ARE THE WIDTH OF A NORMAL SINGLE DOORWAY. PRELIMINARY INVESTIGATION WAS DONE TO DETERMINE IF THE DOOR HAD BEEN WIDENED. WHILE THERE IS SOME EVIDENCE OF REWORKING OF BRICK AT THE JAMB, THIS COULD HAVE BEEN FOR NORMAL MAINTENANCE. THE PRESENCE OF THE LONG CONTINUOUS LINTEL OVER THE OPENING, WHICH APPEARS TO BE ORIGINAL, HAS LED US TO BELIEVE THAT THIS OPENING WAS ALWAYS OF THIS WIDTH, ALTHOUGH WE DO NOT KNOW WHY.


ACCORDINGLY, THE PROPOSED SOLUTION INCLUDES TWO DOOR LEAVES, AS SHOWN IN THE ELEVATION, DRAWING FROM THE DESIGN OF THE GARAGE DOORS BELOW. OUR PREFERENCE WOULD BE TO HAVE THEM OPEN IN AND HAVE A SIMPLE EXTERIOR RAIL PROTECTING THE OPENING. THE UPPER FLOOR SPACE IS ENVISIONED AS AN APARTMENT, ACCESSED VIA THE REAR STAIR, USING THE REFURBISHED EXISTING KITCHEN AND BATHROOM, AND BENEFITTING FROM NATURAL LIGHT THROUGH THE UPPER PANELS OF THE NEW DOORS.

REAR STAIR

A NON-ORIGINAL DILAPIDATED WOODEN STAIR WAS RECENTLY REPLACED WITH A NEW WOOD STAIR FOR SAFETY LEAVING IN PLACE THE FEW REMAINING ORIGINAL POSTS THAT WERE SET AGAINST THE BRICK FAÇADE TO RECEIVE THE STAIR CONSTRUCTION. THESE REMAINING PARTS WILL BE REFURBISHED, AND A NEW STAIR CONSTRUCTED TO MATCH THE ORIGINAL DETAILS AS FAR AS POSSIBLE. THE VERTICAL POSTS WILL HAVE THE SAME CHAMFERED DETAILS AS THE ORIGINAL. IT IS NOT KNOWN WHAT THE BALUSTERS BETWEEN POSTS LOOKED LIKE. SOME PHOTOS OF STAIRS FROM THE PERIOD INDICATE LONG BOARDS PARALLEL TO THE HANDRAILS AND STRINGERS, BUT THESE DO NOT MEET CODE REQUIREMENTS. SIMPLE 1" SQUARE PICKETS ARE PROPOSED HERE AS A MINIMAL AND REVERSIBLE SOLUTION FOR CODE SAFETY. THE ORIGINAL HANDRAIL DESIGN IS ALSO NOT KNOWN BUT HAS BEEN CHAMFERED ON THE EDGES IN DEFERENCE TO THE CHAMFERING ON THE ORIGINAL POSTS.

GENERAL REFURBISHMENT

REFERENCE PHOTOS KEY:



BUILDING LOCATION KEY:

DCRA STAMP:

R STREET N

Oak

GARAGE

BUILDING 3

GRAPHIC SCALE:

2156

Trust

DRAWING: GENERAL DATA SHEET

Live

SHEET #

SOUTH WEST ELEVATION


THE EXISTING ROOF WILL BE REPAIRED WITH NO CHANGE TO EXISTING DESIGN. THE EXISTING WINDOWS WILL BE REPAIRED, AND THE MAGONRY WALLS WILL BE REPAIRED, AND REPOINTED SPARINGLY AS NEEDED.


REFERENCE PHOTOS: EXISTING EXTERIOR ELEVATIONS TO REMAIN

















NORTH ELEVATION









BUILDING #:

C2 GARAGE - PROPOSED ROOF PLAN

| 1/4" = 1"-0" WHEN PRINTED AT 22"/36" |
| 1/8" = 1"-0" WHEN PRINTED AT 11"x1" |






THIS STRUCTURE, BUILT IN 1910 AT THE SAME TIME AS THE GARAGE BUILDING, IS CONNECTED TO THE GARAGE BY A BRICK WALL AND SHARED PASSAGE / WORKSPACE BETWEEN A COVERED OUTDOOR STORAGE AREA ON THE GARAGE AND THE BACK WALL OF THE LAUNDRY AND WORKSHOP BUILDING. NO CHANGES ARE PROPOSED TO THE EXTERIOR OF THE STRUCTURE, AS IT APPEARS TO BE ORIGINAL, OR VERY OLD IN ITS EXISTING STATE. LIKE THE GARAGE, ROOF, WINDOW, AND MASONRY REPAIRS WILL BE COMPLETED. SIGNIFICANT REPAIR WORK WILL BE REQUIRED IN THE BACK WHERE TREE ROOTS AND MOVEMENT OF THE EARTH HAVE DETACHED A PORTION OF THE REAR BRICK WALL FROM THE REST AND OPENED UP LARGE CRACKS.

THE INTERIOR WILL BE REFURBISHED TO HIGHLIGHT THE VERY HANDSOME ROOF BEAM STRUCTURE OF THE FRONT ROOM, AND THE EXISTING BATHROOM WILL BE REPAIRED TO A FUNCTIONAL STATE.

REFERENCE PHOTOS: EXISTING EXTERIOR ELEVATIONS TO REMAIN







PARTIAL SOUTHEAST ELEVATION 2

REFERENCE PHOTOS KEY:

PARTIAL SOUTHEAST ELEVATION



PARTIAL EAST ELEVATION



NORTH ELEVATION (6)

DCRA STAMP:

BUILDING LOCATION KEY: (NTS) R STREET NW

GRAPHIC SCALE:

2156

Live Oak Trust
3238 R Street NW
Washington, DC 20007


DRAWING: GENERAL DATA SHEET

SHEET #:

PARTIAL SOUTHEAST ELEVATION

WEST ELEVATION - ENTRY

(5)



BUILDING LOCATION KEY: (NTS) R STREET NW

DCRA STAMP:

GRAPHIC SCALE:

2156

DRAWING: FIRST FLOOR AND ROOF EXISTING PLANS

Live Oak 7 3238 R Street NW Washington, DC 20007

BUILDING NAME: WORKSHOP AND LAUNDRY

SHEET #:

BUILDING#:
BUILDING 4





NEW FIXTURES IN PLACE OF EXISTING

CI A43

(4A) EXISTING CONDITION IMAGE - MASONRY CRACK

<u>BATH</u>

<u>WORKSHOP</u>

- REPAIR MASONRY CRACK WHERE TREE ROOTS HAVE DAMAGED WALL, SEE IMAGE 4A FOR REFERENCE -

STORAGE

Al A43

> GRAPHIC SCALE:

2156

R STREET NW

DCRA STAMP:

(NTS)

BUILDING LOCATION KEY:

DRAWING: EXISTING ELEVATIONS

Live Oak Trust
3238 R Street NW
Washington, DC 20007

BUILDING NAME:
WORKSHOP AND
LAUNDRY

BUILDING#:
BUILDING 4

SHEET #:

AI WORKSHOP AND LAUNDRY - EXISTING WEST ELEVATION

1/4" : 1'-0" WHEN PRINTED AT 12" 1/35"

1/6" : 1'-0" WHEN PRINTED AT 11" 1/1"

FIRST FLOOR ELEVATION

A2

WORKSHOP AND LAUNDRY - EXISTING NORTH ELEVATION

1/4" = 1'-0" WHEN PRINTED AT 12" '256"

1/8" = 1'-0" WHEN PRINTED AT 11" XIT"





CI WORKSHOP AND LAUNDRY - EXISTING EAST ELEVATION

[A4.3] I/4" : 11-0" WHEN PRINTED AT 22"x36"
I/8" : 11-0" WHEN PRINTED AT II"x17"

FIRST FLOOR ELEVATION

C2 WORKSHOP AND LAUNDRY - EXISTING SOUTH ELEVATION

1/4" : 1'-0" WHEN PRINTED AT 22"266"
1/8" : 1'-0" WHEN PRINTED AT 11"3/1"

BUILDING SCOPE:

THE 1975 RESIDENCE NOW KNOWN AS THE GUARD HOUSE REQUIRES THE MOST REMEDIAL ATTENTION. ITS 1970'S CONSTRUCTION WITH BUTT-JOINED SINGLE-PANE SLOPED GLAZING AND LIGHT-WEIGHT ROOF ASSEMBLY HAS RESULTED IN NUMEROUS WATER PENETRATION AND STRUCTURAL FAILURES. PLUGGED DRAINS IN WINDOW WELLS AND A LACK OF FOUNDATION WATERPROOFING HAVE ALLOWED WATER PENETRATION OF MANY BASEMENT WALLS.

THE EXISTENCE OF A THREE-BEDROOM RESIDENCE ON THE PROPERTY IS A PRECIOUS AMENITY FOR THE PROPERTY, AND THE STREET, AND MAKES THE EFFORT OF RENEWAL WORTHWHILE. AT THE SAME TIME, THE ARCHITECTURE OF THE STRUCTURE IS NOT COMPATIBLE WITH THE REST OF THE SITE, AND ITS CHARACTERISTIC DETAILING HAS INHERENT FLAWS THAT HAVE LED TO THE CURRENT DETERIORATION.

THE PROPOSED SOLUTION MAKES A FEW DELIBERATE ADJUSTMENTS TO THE DESIGN TO REALIGN THE ARCHITECTURE 60 THAT IT CONFLICTS LESS WITH THE REST OF THE BUILDINGS ON THE SITE, AND TO SOLVE THE WATER LEAK CHALLENGES. THE CURRENT VERY STEEP OPEN ROOF OVER THE FRONT PORCH ON THE WEST SIDE. AND THE GLASS AND BRICK ASSEMBLY ON THE SOUTH SIDE, ARE MODIFIED TO A SINGLE LOWER SLOPE ROOF, WHICH WILL WRAP AROUND AND COVER THE AREA ON THE WEST AND SOUTH SIDES, CREATING A SIMPLE AND WELCOMING OPEN PORCH.

THAT LOOKS VERY SIMILAR TO THE EXISTING, BUT SITS SLIGHTLY HIGHER, TO ALLOW FOR BETTER STRUCTURE AND AFTER CONSIDERATION, IT SEEMED THE LEAST OBTRUSIVE PATH WOULD BE TO LEAVE THIS LOW VOLUME INSULATION. IN A LOOP OF DETERIORATION, THE CURRENT ROOF SYSTEM HAS ALLOWED WATER IN, WHICH HAS DETERIORATED EXISTING BEAMS, SUCH THAT THEY SYSTEM SHOULD BE REPLACED. IT ALSO ONLY ALLOWED FOR CONVENTIONAL VERTICAL GLASS WINDOW AND INFILL THE ROOF CUT-BACK CONDITION. 1.5" OF RIGID INSULATION OVER 1.5" LOCK-DECK ROOFING, WITH NO ROOM IN THE CURRENT SYSTEM FOR IMPROVEMENTS.

ON THE NORTH FAÇADE, A SMALL AREA OF SINGLE PANE SLOPED GLAZING OVER THE NORTH END OF THE KITCHEN SPACES GENERALLY UPDATED. WITH BE REPLACED WITH METAL ROOF SLOPED TO MATCH THE NEW FRONT PORCH. THE WATER INFILTRATION THAT

HAS OCCURRED AT THE TOP OF THE EXISTING SLOPED GLAZING HAS CAUSED INTERIOR WOOD BEAMS TO ROT, AND A PORTION OF THE NORTH EXTERIOR BRICK FACADE TO CRACK AND DISPLACE DOWNWARD. THE INTERIOR STRUCTURE WILL BE REPAIRED AND REPLACED AS NECESSARY, AND THE BRICK RESTORED TO ITS ORIGINAL POSITION AND REPOINTED. THE EXISTING SLIDING DOORS AND FIXED WINDOWS WILL BE REPLACED WITH NEW FIXED WINDOWS.


ON THE SECOND FLOOR AT THE SW CORNER THERE IS A SITTING ROOM WITH WINDOWS ON THE EAST AND SOUTH SIDES. THE SOUTH WINDOW FITS UNDER A SHED DORMER WITH A LOW WINDOW HEAD (JUST OVER 61). THE EAST WINDOW IS NOT COMPATIBLE WITH THE REPOSITIONING OF THE HOUSE AND IS PROPOSED TO BE REMOVED. TO PROVIDE GENEROUS LIGHT INTO THE ROOM, THE SHED DORMER IS LIFTED ALONG THE SOUTH EDGE TO ALLOW TALLER WINDOWS.

AT TWO EXISTING WINDOW WELLS AND AN EXISTING EXTERIOR BASEMENT STAIR AROUND THE PERIMETER OF THE HOUSE, EXISTING PLEXIGLASS COVERS WILL BE REMOVED, AND EXISTING DRAINS OPENED AND CLEANED TO ALLOW WINDOW WELLS TO DRAIN PROPERLY.

THERE IS A ONE-STORY ADDITION ON THE NORTH SIDE OF THE HOUSE, SET HALF-WAY BETWEEN THE FIRST FLOOR THE OVERALL ROOF WILL BE REPLACED, INCLUDING ITS STRUCTURE, RESULTING IN A STANDING SEAM METAL ROOF AND THE BASEMENT, WITH A SLOPED GLAZING WINDOW ON THE WEST AND SLIDING PATIO DOOR ON THE EAST SIDE. ESSENTIALLY AS-IS, BUT TO REPLACE THE LARGE SLOPED-GLAZING WINDOW AND ITS CUT-BACK ROOF WITH A NEW

> ALL WINDOWS AND DOORS WILL BE REPLACED, DUE TO FAILURE AND DETERIORATION, KEEPING EXISTING MULLION PATTERNS, UNLESS NOTED OTHERWISE ABOVE. INTERIOR KITCHENS AND BATHS WILL BE RENOVATED, AND INTERIOR

REFERENCE PHOTOS KEY:



BUILDING LOCATION KEY: (NTS)

DCRA STAMP:

2156

Oak

drawing: GENERAL DATA SHEET

GUARD HOUSE

BUILDING#:
BUILDING 5

R STREET N

GRAPHIC SCALE:

Trust

Live

SHEET #

REFERENCE PHOTOS: EXISTING EXTERIOR ELEVATIONS TO REMAIN







SE ELEV. - PLEXIGLASS STAIR COVER



EAST ELEY. - PLEXIGLASS STAIR COVER



PARTIAL NORTH EAST ELEY. - VIEW FROM STREET (6)



PARTIAL NORTH EAST ELEVATION



PARTIAL NORTH EAST ELEVATION 8

SOUTH ELEVATION

