

APPLICATION AND REFERRAL TO THE US COMMISSION OF FINE ARTS FOR OLD GEORGETOWN REVIEW

OG	

HPA

In accordance with the Old Georgetown Act of 1950 (Public Law 808, 81 st Congress) this application/transmittal is being transmitted to the US Commission of Fine Arts (CFA) for review and recommendation before a building permit can be issued. Work in Georgetown is also subject to a coordinated historic preservation review under the DC Historic Landmark and Historic District Protection Act of 1978. These reviews are initiated with the completion and submission of this form.
THIS IS A REQUEST FOR THE FOLLOWING REVIEW BY THE COMMISSION OF FINE ARTS:
CONCEPTUAL REVIEW to receive guidance at the early stages of design
PERMIT REVIEW to receive a recommendation on building permit application No.
1. OWNER, APPLICANT, AND PROPERTY INFORMATION
Project Address: 1636 33rd ST NN DC, 20007
Square: 1278 Lot: 0226 (To find your square and lot, see www.propertyquest.dc.gov)
Property Owner's Name: Maggic Earll
Owner Address (if different from project address):
Owner Phone (202) 468-3461 Owner Email: Margaret, Carllo concast, net
Owner Phone (202) 468-3461 Owner Email: Margaret, Carlle concast, net Applicant's Name (if different from owner): Architectural Window Corp
Agent's Capacity: Tenant Architect Contractor Contract Purchaser Expediter Other
Agent Address (if different from owner): 1247 Wisconsin Arc, Nh, DC 20007 (202) Agent Phone: 657-2408 Agent Email: paul. d @ a-ch-wirdow, Com
Agent Phone: 157-2408 Agent Email: David @ a-ch-window. Com
I am currently the owner of the property
I am a homeowner currently receiving the DC homestead deduction for this property
A lam an authorized representative of the property owner
I am or represent a potential purchaser of the property
2. SUBMISSION MATERIALS FOR THE COMMISSION OF FINE ARTS AND HISTORIC PRESERVATION REVIEW
Drawings must be submitted in two formats: <u>electronic</u> (3MB maximum size, by email or flash drive) and <u>TWO paper</u> sets (11" x 17" for conceptual review) of the following:
Drawings, including, as applicable, elevations, details, and a site plan sufficient to illustrate the footprint, location, height, massing, design, and materials of the proposed work and its surrounding
context; site plans should show the existing footprint of the property and adjacent buildings. comprehensive exterior photographs of the building, structure, or site and its context (showing adjacent buildings, immediate surroundings, and the areas of proposed work)
For more information on submission requirements, see www.cfa.gov or contact the CFA staff at 202-504-2200
3. PROJECT DESCRIPTION (CHECK ALL THAT APPLY)
Addition Addition Atterior Alteration or Repair New Construction Subdivision Other
Briefly describe the nature of the project:
Peplace Rear Windows

	YES	No	UNSURE	
Is the proposed work visible from a public street or alley?		A		
Will there be work on the front of the building or in the front yard?		A		
Does the project include work in public space?		Ø		
Does the project include removal of roof or floor framing or bearing walls?		Ø		
Is this a Fair Housing Act request for "reasonable accommodation"?		à		

4. ADDITIONAL INFORMATION FOR LARGER PROJECTS

For renovation or new construction projects exceeding 20,000 square feet, attach a full narrative description indicating the general nature of the project, program of uses, estimated gross floor area by use, number of residential units, scope of preservation work, and any other pertinent features or benefits, including aspects of sustainability. *Homeowners proposing work on their own house do not need to provide this information*.

5. EASEMENTS	YES	No	UNSURE
Is there a conservation easement on the property?		A	
If yes, have you discussed the project with the easement holder?			
6. COMMUNITY CONSULTATION	YES	No	UNSURE
Have you shared project information with abutting neighbors?		Ø	
Have you contacted the affected Advisory Neighborhood Commission (AN	NC 2E)?	ø	
Have you contacted any neighborhood community organizations? For more information about project review by ANC 2E, see www.anc2E.com or c	call the ANC at 202-3	38-7427	
7. ZONING REGULATIONS AND CONSTRUCTION CODE	YES	No	UNSURE
Will the project cause a change in building footprint or lot occupancy?		Ø	
Are any zoning variances or special exceptions required for the project?		Ø	
If yes, have you discussed the project with the Zoning Administrator	r? 🗆	网	
If yes, have you discussed the project with the Office of Planning?		ø	
Is any building code relief required for the project?		A	
Briefly describe the nature of any zoning variances or code relief being s	ought:		

8. CERTIFICATION

I hereby certify that the information given in this application is true and accurate. If applying as an agent of the owner, I certify that I have the owner's permission to make this application.

Signature:

(Fur AWL)

Date: 8

When completed, submit this form with all plans, photographs, and other attachments to the Historic Preservation Office (HPO) desk at the DC Permit Center, Department of Consumer and Regulatory Affairs, 1100 4th Street SW, 2nd floor. Upon review of this submission, CFA or HPO staff may contact the owner or agent for consultation, and may request additional information if determined necessary to review the project.

Referral to CFA or the Historic Preservation Review Board, if required, may be deferred if information is not received within sufficient time to allow staff evaluation and preparation for review. All application materials are part of the public record and are made available to the public for inspection. For more information, see www.cfa.gov or www.preservation.dc.gov.



Historic Preservation Office DC Office of Planning (202) 442-8800 historic.preservation@dc.gov

District of Columbia Office of Planning





Paul DonVito

1247 Wisconsin Ave, NW Washington, DC 20007 **Phone:** 877-286-1881 **Fax:** 888-933-9765 **Cell:** 202-657-2408 **Email:** paul.d@arch-window.com www.arch-window.com

Rear Window Replacement Project 1636 33rd St, NW REVISED 8.24.22

Owner: Maggie Earll Owner Contact: 202-468-3461 / Margaret.earll@comcast.net Lot/Square – 1278 / 0226

Project Overview

History of Home:

The pressed brick end unit row home at 1636 33rd St, NW was designed and built in 1925 by architect/builder J. W. Powell. It was part of the early 20th century development of Georgetown leading toward Burleith. It is a simple, practical flat front home with 6/1 wood DH windows and a colonial revival front door surround

Rear Windows - Not Visible from Street:

Replace three existing wood windows, along with rotting and failing window frames, in the rear of home. None are visible from a public street.

All three existing windows appear to be original to the home. The three existing windows are in extremely poor condition, due to age, poor maintenance over many years.

We are proposing historic replica wood window replacement units constructed of sapele mahogany. Proposed window units will have Insulated glass with simulated divided light. The exterior profile will be simulated putty glaze, closely replicating the exterior putty glaze profile of the original sash. The design and lite pattern of the proposed windows are based on the existing windows, and replicate both the profiles and dimensions of the original windows. We will match the existing brickmould and mull profile.

There will be no vinyl to the exterior.

We are proposing:

- Full frame replacement (removing all existing window to the masonry) / double hung window unit with top sash fixed and lower sash operable
- All proposed windows are 6 over 1
- All wood to the exterior
- No changes to the masonry
- Brickmould to match the existing brickmould (which we believe to be original

Window Type (drawings enclosed):

Dallas Millwork double hung window unit (top sash fixed), sapele mahogany, 1-3/4" thick sash beveled to the exterior, Low E insulated glass with Argon, simulated divided lite with bronze spacer bar and simulated putty glaze (light pattern listed below), 5-1/4" jambs, historic sill nose, brickmould casing to match original brickmould casing.

Enclosed Documents and photos:

- 1. Aerial View of property.
- 2. Photos of building elevation showing the windows to be replaced.
- 3. Photos of existing window conditions.
- 4. Photos of existing brickmould casing.
- 5. Shop drawings of proposed replacements.
- 6. Selected Shop drawings showing relationship of existing masonry to new windows

1636 33rd STREET (REAR) SUPPLEMENTAL PHOTOS REVISED 8.24.22

SECTION 1 – LOCATION AND CONTEXT OF HOUSE



AERIAL VIEW OF LOCATION



CONTEXT ON 33RD STREET

SECTION 2 – PLACEMENT OF REAR WINDOWS TO BE REPLACED

The 2 rear window units we are proposing to replace cannot be seen from a public street or alley.



Existing:

Second Floor - Window Units A, B - Original 6 over 1 wood windows. One unit is a twin unit, the other is a single window unit. Existing sashes and frames are severely rotted. One sash has failed completely. Most of the wood joints are also failing. The frames are dry rotted.

Proposed

Window Units A, B to be replaced with sapele mahogany 6 over 1, all wood, Dallas Millwork, Inc full units, insulated glass, no vinyl to the exterior and brickmould to match.

SECTION 3 – CURRENT CONDITION OF WINDOWS TO BE REPLACED

The current rear windows, particularly the sashes, are in very poor condition, severely rotted, out of square, and despite the owner's well-intentioned attempts to maintain them, the fact is that they are highly susceptible to both direct rain and snow as well as intense summer sun. These factors have taken their toll.

Note – We would have preferred to restore original sashes and frames (and we do that work from time to time) but in this case it is our professional judgment that these windows are beyond restoration due to the issues listed above.

Rear Second Floor original window specific issues include:

- 1. Sashes are severely rotted
- 2. Many wood joints are failing
- 3. Frames are both wet and dry rotted
- 4. Lower portions of brickmould are severely rotted and compromised

DETAILS OF FRAME ROT / SASH ROT ISSUES



INTERIOR UNIT A (lower sash, twin window left side from INT) - Side rail is rotted and has completely separated from lower rail. Wood joinery has failed. This window sash has been pushed back together, but it previously collapsed on the owner as she attempted to open it.



EXTERIOR UNIT A (lower sash, twin window left side from INT) – Exterior view of same issue. Total failure of joinery.



INTERIOR UNIT A (upper sash, twin window right side from INT) - Meeting rail is rotted and splitting. Attempts at repairs with bondo have failed.



INTERIOR UNIT A (Lower sash, twin window right side from INT) - Lower rail is rotted and splitting from side rail. Failure of joinery. Both upper and lower sash have signifcant rot issues



EXTERIOR UNIT A (Lower sash, twin window right side from INT) - Sash lower rail is severely rotted and has separated from side rail.



EXTERIOR UNIT B (Upper sash, bathroom window right side from INT) - Sash meeting rail is rotted and splitting and has separated from side rail. Sash is in danger of collapse.



INTERIOR B (Upper sash, bathroom window right side from INT) - Sash meeting rail is rotted and splitting and has separated from side rail.

KEY DIMENSIONS OF ORIGINAL WINDOWS (to be replicated)

Existing Lower Rail: 3-1/2 face Existing Stiles: 1-3/4" face Existing Upper Rail: 1-3/4" face Existing Meeting Rail: 1" face Existing Muntins - 7/8"



Lower Rail

Stiles





Muntin

MULL AND BRICKMOULD PROFILES TO BE REPLICATED





Existing mull profile to be replicated





Existing brickmould to be replicated

ARCHES

Flat decorative arches will be replicated on site with sapele mahogany. Here is a similar window we replicated at the OGB approved job at 1526 32nd St, NW









DALLAS

Dallas Millwork Inc.
PO Box 549 Hiram, GA. 30141
770-943-3909 770-943-3900 FAXArchitectural Window
Corp.-Washington DC.DRAWING #
ER5172201APPROVED BY:
X1636 33rd StreetDATE:5-17-22XREV. #:
REV DATE:





ROUGH OPENING MEASUREMENTS ARE DETERMINED BY ADDING 1" TO THE "OSJ" WIDTH AND ¹/₂" TO THE "OSJ" HEIGHT



Dallas Millwork Inc.
PO Box 549 Hiram, GA. 30141
770-943-3909 770-943-3900 FAXArchitectural Window
Corp.-Washington DC.DRAWING #
ER5172201APPROVED BY:
X1636 33rd StreetDATE:5-17-22XREV. #:
REV DATE:

